

Message Text

UNCLASSIFIED

PAGE 01 MOSCOW 19034 101558Z
ACTION FBOE-00

INFO OCT-01 EUR-12 ISO-00 A-01 SMS-01 SSO-00 SY-05
/020 W

-----028634 101600Z /44

O 101534Z AUG 78
FM AMEMBASSY MOSCOW
TO SECSTATE WASHDC IMMEDIATE 5393

UNCLAS MOSCOW 19034

E.O. 11652: N/A

TAGS: ABLD, AFSP, ASEC/NSU, UR
SUBJECT EMBASSY RECONSTRUCTIONM PROPERTY NO.
L01001, ELECTRICAL RENOVATIONS

REF: (A) STATE 200055, (B) A/FBO-FBO/M 8/8/78 TELECOM,
(C) MOSCOW 18380

1. BILL OF MATERIALS FOLLOWS SEPTTEL. SCOPE OF WORK
WAS PROVIDED IN REFTEL (C). AS EXPLAINED A DETAILED
SPECIFIC WORDING SUITABLE FOR LUMP SUM COMPETITIVE
BIDDING IS NOT CONSIDERED FEASIBLE DUE TO WIDE RANGE
OF EXISTING CONDITIONS REQUIRING REMEDIAL WORK. THE
OTTO LANG ESTIMATE WAS OBTAINED BY ON-SITE ROOM TO
ROOM SURVEY.

2. REGARDLESS OF WHICH CONTRACTOR IS SELECTED PRO-
JECT SUPERVISOR RECOMMENDS UPSET PRICE, COST INCURRED
BASIS IN ORDER TO AVOID TIME DELAYS WHICH DUE TO
SAFETY ASPECTS WOULD NOT BE ACCEPTABLE TO EMBASSY.

3. PLEASE BEAR IN MIND THAT POST HOUSING LIMITATIONS
ONLY PERMIT USE OF ONE THREE BEDROOM APARTMENT.
AUSTRIAN ELECTRICIANS SLEEP TWO PER BEDROOM. IF THIS
IS FOUND UNSUITABLE FOR U.S. ELECTRICIANS, THEN HOTEL
UNCLASSIFIED

UNCLASSIFIED

PAGE 02 MOSCOW 19034 101558Z

ROOMS MUST BE EMPLOYED.

4. CONCEPT USING U.S. CONTRACTOR AS MENTIONED REFTELS
(A) AND (C) IS WELCOMED PROVIDED UNDUE DELAY IS AVOIDED.
REFTEL (A) PARA 2 INTRODUCES EVALUATION OF LANG'S
INSTALLATIONS NOT PREVIOUSLY KNOWN HERE. HIS MOSCOW
WORK MEETS U.S. STANDARDS, IS BEING DONE UNDER DAILY

FBO/M SUPERVISION, AND WHERE ROUTINE ERRORS OCCURRED
WERE PROMPTLY CORRECTED.
TOON

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: Z
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 10 aug 1978
Decaption Date: 20 Mar 2014
Decaption Note: 25 YEAR REVIEW
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978MOSCOW19034
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780327-1116
Format: TEL
From: MOSCOW
Handling Restrictions:
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780878/aaaacngg.tel
Line Count: 65
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 50cb5b65-c288-dd11-92da-001cc4696bcc
Office: ACTION FBOE
Original Classification: UNCLASSIFIED
Original Handling Restrictions: ONLY
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: ONLY
Reference: 78 STATE 200055, 78 MOSCOW 18380
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 05 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1779226
Secure: OPEN
Status: NATIVE
Subject: EMBASSY RECONSTRUCTIONM PROPERTY NO. L01001, ELECTRICAL RENOVATIONS
TAGS: ABLD, AFSP, ASEC, UR, NSU
To: STATE
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/50cb5b65-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014